

12.01.11 Case Study : Curb Repair

In January 2011, Miller Capilano Highway Services were commissioned via our Canadian distributor, Nuna Innovations, to trial the use of Concrete Cloth (CC) to repair damaged curbs. The void in the curb was first filled and then lined with CC8. The CC was wrapped around the curb and fixed into position using standard concrete anchor screws before hydrating. Following the success of the trial, which was completed in under two hours, a number of other curb sites are being considered for refurbishment using CC.



Damaged curb section at main junction



Damaged curb section detail



Completed, refurbished curb section